0019



State of Utah DEPARTMENT OF NATURAL RESOLUTION

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director
Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340

INSPECTION REPORT

Of De	RR	F
9		

PER Per	MIT NO.: <u>ACT/015/032</u> Inspection Damittee and/or Operators Name: <u>Genwal Coal</u>	ite:	August	9, 1991	
Rue	iness Address: P.O. Box 1201	<u> </u>			
Cit	y: Huntington State: Utah		71	0/527	
	o Namo: Cuardall Carry			p: <u>04327</u>	
Cou	e Name: <u>Crandall Canyon</u>				
Typ	nty: <u>Emery</u> State: <u>Utah</u> e of Mining Activity: Underground <u>XX</u> S	6		O+ l	
1 yp	e of mining Activity: Underground XX S	urtace_		otner	
COM	pany Official (s): <u>Jay Marshall</u>				
Sta	te Officials (s): Stephen J. Demcak	10.00		. V.	
I 1 m	e of Inspection: $9:00$ (X) a.m.() p.m. to	12:00	<u>()a</u>	.m. (X)	p.m.
Par	tial XX Complete: Date of Last Inspe	ction:	July	26, 1991	
wea	ther Conditions: Warm 80's				
Acr	eage: Permitted $\overline{527.4}$ Disturbed $\overline{5.6}$ Regr	aded U.	5	Seeded_).5
Bon	ded 5.6 Enforcement Action: None	······			
•	COMPLIANCE WITH PERMITS AND PERFORM	RMANCE	STAND	ARDS	
		YES	<u>NO</u>	N/A	COMMENTS
1.	PERMITS	/ v 1	1	١ / ١	(v)
2.		_ \ _\	}	\	_ X_ \
3.	SIGNS AND MARKERS TOPSOIL	\	}	\	\\
3. 4.		(<u>X</u>)	ι) ()	(<u>_</u> X_)
4.	HYDROLOGIC BALANCE:	, ,	,		
	a. STREAM CHANNEL DIVERSIONS	((·) ()	(;
	b. DIVERSIONS	()	}) ()	()
	c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	<u> </u>	()	(_X_)
	d. OTHER SEDIMENT CONTROL MEASURES	()	}) ()	()
	e. SURFACE AND GROUNDWATER MONITORING	()	(()	()
_	f. EFFLUENT LIMITATIONS	()	() ()	()
5.	EXPLOSIVES	()	() ()	()
6.	DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	() ()	()
7.	COAL PROCESSING WASTE	()	() ()	()
8.	NONCOAL WASTE	()	() ()	()
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	()	() ()	()
0.	SLIDES AND OTHER DAMAGE	()	() ()	()
11.	CONTEMPORANEOUS RECLAMATION	()	() ()	()
2.	BACKFILLING AND GRADING	()	() ()	()
3.	REVEGETATION	()	() (()
4.	SUBSIDENCE CONTROL	(() ()	()
5.	CESSATION OF OPERATIONS		<u>`</u>	i = i	()
6.	ROADS	//	`	,	·
	a CONSTRUCTION	()	() (()
	b. DRAINAGE CONTROLS	(<u>`</u>	<u> </u>	()
	c. SURFACING	()	`	$\langle \cdot \rangle - \langle \cdot \rangle$	}—;
	d. MAINTENANCE	}'	}	() ()	}
7.	OTHER TRANSPORTATION FACILITIES	}	}	()(}{
8.	SUPPORT FACILITIES	()	ι	, ()	ι,
٠.	UTILITY INSTALLATIONS	(x)	() ()	(v)
	OITETII THOIMELMITUNO	(X)	l	, ()	(X)

INSPECTION REPORT COMMENTS (continuation sheet)

Page __2_of_2_

PERMIT	NO	ACT,	/015/032	1	INSPECTION	DATE	_Augus	t 9, 199	1
(Commer	nts a	re	Numbered	to	Correspond	d with	Topics	Listed	Above)

- 1. Permits An AVS check was made at Genwal. The mine submitted new documentation on direction and ownership to DOGM prior to inspection. An ad will be placed in the newspaper during the upcoming week. I viewed this article during inspection. The ad will run four consecutive weeks.
- Topsoil The concern is in the winter during snow removal from the haul road. The encroachment on the topsoil pile in particular the use of salt may jeopardize the quality of the pile. This encroachment will correspond with the quality of show fall. A higher barrier between road and topsoil pile is suggested.
- 4c. Sediment Ponds and Impoundments - At the time of inspection, the pond was not discharging and no problems were noted.
- 18. Support Facilities and Utility Installations - The crusher building was emitting coal dust which was very unnoticeable. Additional water may be needed with dust suppression additive.

Copy of report:

Genwal Coal Co. Mailed to:

Joe Helfrich (DOGM) Brian Smith (OSM) Mailed to SLC for:

Filed to:

Inspectors Signature and Number:

ph- Jentle

Date: